

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

CROCKETT FARM, BARN
1056 Fort Casey Road
Coupeville vicinity
Island County
Washington

HABS WA-246-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

- | | |
|------------|--|
| WA-246-A-1 | CROCKETT BARN SOUTH AND EAST FAÇADES, LOOKING NORTH. The Crockett barn was constructed into the sloping landscape. The Pennsylvania Bank Barn construction style allows for access at ground level on both the upper and lower floors. The Crockett granary is visible on the right hand side of the photograph. Currently a property line runs between the two buildings. |
| WA-246-A-2 | LOWER LEVEL OF CROCKETT BARN, LOOKING SOUTH. The barn is built on a fieldstone foundation with a heavy-timber, mortise and tenon wood construction. A bank of window openings spans the south and east walls. Every other opening is covered with an operable shutter that is hinged to the window header above. |
| WA-246-A-3 | CROCKETT BARN'S UPPER LEVEL, LOOKING NORTHEAST. This image shows the construction of the three interior bents, the south end of the loft and stairs, the ladder leading to the cupola, and the dance floor added in 2006. |

CROCKETT FARM, BARN
HABS WA-246-A
INDEX TO PHOTOGRAPHS

WA-246-A-4

DETAIL OF CROCKETT BARN WALL CONSTRUCTION,
UPPER LEVEL. The wall construction of the Crockett barn
includes a layer of diagonal sheathing that is exposed on the
interior.